





U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Final Site Restoration Agreement

I, Rosa Loza, owner of the subject property located at 4916 Fillmore Street, Denver County, Colorado, hereby voluntarily, under no threat, accept the amount of \$175.00 from the United States Environmental Protection Agency (EPA) in lieu of any further work or monies received regarding the subject property by the U.S. EPA, the United States Army Corps of Engineers, or it's contractors. These funds are considered payment in full for the damaged water meter located at the subject property.

Property Owner's Signature

Date

Contractor's Signature

Date



CUSTOMER'S RECEIPT

KEEP THIS RECEIPT FOR YOUR RECORDS	ADDRESS 4914	Rosa Jo FILLMORE	sa st.		SEE BACK OF THIS RECEIPT FOR IMPORTANT CLAIM INFORMATION NOT NEGOTIABLE
09060	NUMBER 117	2005-09-27	POST OFFICE 802161	\$175.00	019

Scan money order only

UNITED STATES POSTAL SERVICE.
POSTAL SERVICE.

CUSTOMER'S RECEIPT

KEEP THIS	PAY TO,				SEE BACK OF THIS RECEIPT FOR IMPORTANT CLAIM
RECEIPT FOR	ADDRESS				INFORMATION
Your Records	C. O. D. OR USED FOR				Negotianle Negotianle
0906	098117	YEAR, MONTH, DAY 2005-09-27	Post OFF 90216		CLERK 019
	SERVICE. P	OSTAL M	ONEY (ORDER	15-800
	RIAL NUMBER	YEAR, MONTH, DAY	POST OFF	н с в. 🖖 - и.в. Do	LLARS AND CENTS
09060	1098117	2005-09-2 7	80216	1 1	11752004
	AMOUNT	ONE HUNDRED	SEVENTY-FI	WE MILLARS	£ 00¢******
PAY TO	:		NEGOTIABLE	ONLY IN THE U. SEE REVERSE V	S. AND POSSESSIONS
ADDRES5			FROM		CLERK 019
			ADDRESS	r inga ar	
C O.D. NO OR					J
:: 00000	2800 51:	090600	38117#		_

*** Large bock Large Rock DIRT shed 22'X15' 15×16 Rose bushoes GARAGE gal 50 36 X 31' 13×11 Gare DR INEWRY House Larye Rock, SPAVEL 4916 Fillmore sprinkler System eose Bush goes Bush goes DRIVENAY GAVEL 7'X37' 2 ravel udelel 32' X 36'





U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Rosa Loza
Property Address	4916 Fillmore Street
Property Identification Number	3861

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)			
Trees			
Itemized shrubs/bushes	7	\$12.00	\$84.00
Total			\$84.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of \$84.00 has been received by the owner in the form of a replacement certificate, #152.56, to be utilized at Paulino's Gardens, 6300 N. Broadway, Denver, CO 80216.

Property Owner's Signature

Date

Contractor's Signature

Date



Project Besources Inc.

Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: 386		
Property Address: 4916 Jellmore	27	
Owner: Pasa Kom		
Phone: 720-256-5739		
Restoration Items in Question:		
Item:	,	
Item:		
· · · · · · · · · · · · · · · · · · ·		
Additional Comments:		7
	,	
		ì
·		l
I agree restoration is completed, except as noted		
I do not agree restoration is completed .		
I agree that the sprinkler system is working properly following reinstallation by contractor		•
Roselem Elistos	Dran Kurin	8/18/08
Owner's Signature Date	Contractor's Signature	Date



riope	ity Acces	33 CHEC	Kilst S	prinkler-Sixten
Property ID: 3.766		□ work	STARTED	ON: / /
Property Address: 4916 Fill more St.			COMPELTED	ON://_
				<u> </u>
Property Owner: Kosa Loza	(Property R	enter: Carme	n
Mailing Address:		Home Phor		
4916 Fillmore 5t.		Fax:		
		Cell/Pager:		
Home Phone: 720 - 256 - \$573	7	Additional	Information:	
Fax:		<	Sa-in Vlac S.	مار
Cell/Pager:		-	óprinkler sy.	ortum
Notification Letter	Sent: 10	1810H	By: A. Jame	25
Access Agreement	Signed: 📙	102104	By: Rosa Lo	
Restoration Agreement	Signed: 1	111105	By: Rosa L	-0 2 -G
☐ Topsoil Sampling (if applicable)	/_	_/	By:	
☐ Disposal Sampling (if applicable)		_/	By:	
Garden Sampling (if applicable)	/	_/	By:	
Utility Clearance	Called:	//	By:	
☑ Video/Photos (Before)	On:/	11105	By: A. James	/J. Rever
☐ Video/Photos (During)	On:/	/	Ву:	
☐ Video/Photos (After)	On:/	/	ву:	
☐ Video/Photos (30-Day)	On:/	/	By:	
☐ Property Completion Agreement	Signed:	//	By:	
☐ Final Report	Issued://		Ву:	
Air Monitoring (as applicable)				
	//_	By:		
Results:		-1		··········
	, ,	TD-11		
Community Crew On:	<u>//</u>	By:		
	//	By:		
Results:				



Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 386 Property Address: 4916 Fillmore 5t.

Owner: Rosa Loza

Phone: 720-256-5737

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	
	Tires in book
Item:	
	Cars in drivery
item:	
	Wood table in sack
ltem:	
	0001
item:	
	Any plants to be source
Item:	, · · · · · · · · · · · · · · · · · · ·
	Truck topper behind garage
Item:	
Item:	



Items To Be Removed By Contractor During Remediation And Not Replaced (Use additional sheets as necessary)

Item:	
Item:	NIA
item:	
item:	
Item:	
Item:	·
Item:	· · · · · · · · · · · · · · · · · · ·
Item:	Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)
·	(Use additional sheets as necessary)
·	
Item:	(Use additional sheets as necessary) Sprinkler System
Item:	(Use additional sheets as necessary)
Item:	(Use additional sheets as necessary) Sprinkler System
Item: Item:	(Use additional sheets as necessary) Sprinkler System



Landscape Inventory (Use additional sheets as necessary)

ltem	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	3,658	Square Feet	
Number of trees > 2 inch trunk diameter	6		·
Number of trees < 2 inch trunk diameter	· Jo		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	Sprinkler System		Zones:
Number of and total size of all gardens / flower beds.	# Of Beds:		Fr ² Of Beds:
Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft ² Of Gardens:



Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	s	Total Ft ² Of Beds To Be Replaced With Certificate: Vonche 7 Rose busines
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be placed by the contractor.		Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.		SF	Total Ft ² Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Ft ² :	SF	Sod: Brown Mulch: Red Mulch:
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch:	SF	Red:



Project Resources Inc.

item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock:	SF	Large: Medium: Small (pea gravel): Driveway Gravel:
Agreed upon area to be eplaced with no roundcover.	Total Ft ² With No Groundcover:	÷	

		ructions:

Sprinkler system
12ep101ce

7 Rose bushes



<u></u>	Additional Comments / Ins	structions Continued:	
	÷		
	÷		1
	,		
	1		
Check the box i	f Owner does not want PRI to do	cument interior foundati	on walls and nossible
pre-existing damag	e. By checking this box PRI is cluding foundation cracks or fissur	not responsible for any	damage done to the
☑ I agree	I do not agree	I agree	☐ I do not agree
amer	Segar 1-11-05	Omen a	1-11-05
Owner's Signature	Date	Contractor's Signature	Date



RESTORATION CHANGE ORDER VB/I-70

Property ID # <u>386 </u>
Property Address 4916 Villmore St.
Owner Name Rosa Loya
Date 6 27 05
Comments
Change 15x16 soil in buck yard. by flace to sod
Owner Signature Ren San Contractor Signature from Kann
Throight Document Inc

Real Property Records

Date last updated: Thursday, January 06, 2005

© Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

View Map/Historic District Listing for this Property
Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential

Parcel: 0213316004000

Name and Address Information

Legal Description

LOZA, ROSA

4916 FILLMORE ST

CAWKERS ADD B8 L25 & 26

RESIDENTIAL

DENVER, CO 80216

Property Address:

Tax District

4916 FILLMORE ST

DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	17700	1410		
Improvements	113500	9040		
Total	131200	10450	0	10450
Prior Year				
Land	17700	1410		
Improvements	113500	9040		
Total	131200	10450	0	10450

Style: One Story

Year Built: 1947

Building Sqr. Foot: 694

Bedrooms: 2

Baths Full/Half: 1/0

Basement/Finished: 0/0

Lot Size: 5,900

Zoning: R1

Reception No.: 2004147701

Recording Date: 07/13/04

Document Type: Warranty

Sale Price: 135000



DERECHO A ENTRAR LA PROPIEDAD

El otorgante (dueño/a de la propiedad) le da permiso y autoriza la Agencia para la Protección del Medio Ambiente de los Estados Unidos (EPA) y/o a sus representantes autorizados (Cesionario) a entrar y a llevar a cabo algunas actividades ambientales en la propiedad a continuación:

Dueño/a de la Propiedad: Rosa Loza		Número de Teléfono: 726 - 256 - 5737	
Propiedades Cubiertas por este	Dirección:		
Acuerdo:	Dirección:		

PROPÓSITO DE LAS ACTIVIDADES AMBIENTALES

La EPA solicita el acceso a tomar muestras de tierra y a remover la tierra en su propiedad que tiene concentraciones altas de arsénico y/o plomo que podrían ser peligrosos a su salud. La tierra será removida y el(las) área(s) excavada(s) serán reemplazadas con materiales limpios. Este trabaja estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de la EPA contactará al Otorgante personalmente para discutir el trabajo que se va a realizar en la propiedad del Otorgante. El Otorgante tendrá la oportunidad de examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termine, el Otorgante revisará el trabajo, confirmará su terminación y cumplirá con su aprobación. Después de la terminación del trabajo, el Otorgante recibirá un documento escrito por la EPA que indicará que la propiedad ha sido remediada.

ACCIONES DE LA ACTIVIDAD AMBIENTAL

Por su firma de este Acuerdo de Acceso, el Otorgante concede el EPA, sus empleos, contractores y subcontractores el derecho a entrar la propiedad, en tiempos razonables y sin noticia anterior, para el único propósito a realizar el trabajo aquí descrito. Este acceso debería persistir en efecto hasta que el trabajo haya sido terminado. El Ortogante también está de acuerdo con:

Página 1 of 2	
---------------	--



RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name:			Phone: 720) 256-5737
Rosa Loza			123/23
Addresses of	Address:	4916 Fillmo	re St
Properties covered by this Agreement:	Address:		
	Address:	· · · · · · · · · · · · · · · · · · ·	

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed. The Grantor will have an opportunity to review and approve the planned soil removal and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

- Remover obstrucciones, incluyendo botes, remolque, vehículos, juguetes de niños, montones de madera, casas de perros, etc.
- Remover bulbos de flores, u otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener el reemplazo de vegetación, incluyendo la aplicación de fertilizante, subsecuente a la riega inicial por la EPA, a menos que el uso de agua esté restringido por la Junta de Agua de Denver.
- Seguir las recomendaciones de la guía de Salud y Seguridad de la EPA;
- Si la propiedad es rentada, asistir a la EPA a obtener la aprobación del inquilino para tener acceso a la propiedad dende se va a llevar a cabo el trabajo, si acaso la EPA no logra obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad, incluyendo el área exterior y interior del edificio.

ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividad o trabajo hecho, o equipo que va a llevar a cabo las actividades en la propiedad, o arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor llame al centro de comando de VB/I-70 a (303) 487-0377.

Si, yo permito acceso a mi propiedad.		☐ No permito acceso a mi propiedad.	
Rosu Som Firma		Firma	Fecha
	esente durante de cualquie e un sistema de regar plant		em).
	Página 2 (of 2	

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

☐ I grant access to my properties		I do not grant acc	ess to my properties
Signature	Date	Signature	Date
·	e present during any samp a working sprinkler syste	ling that is required. m that will need to be replaced	
	Page 2	of 2	





Real Property Records

Date last updated: Thursday, December 30, 2004

3 Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential

Parcel: 0213316004000

Name and Address Information

Legal Description

LOZA, ROSA

4916 FILLMORE ST

CAWKERS ADD B8 L25 & 26

RESIDENTIAL

DENVER, CO 80216

Property Address:

Tax District

4916 FILLMORE ST

DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	17700	1410		
Improvements	113500	9040		
Total	131200	10450	0	10450
Prior Year				
Land	17700	1410		
Improvements	113500	9040		
Total	131200	10450	0	10450

Style: One Story

Year Built: 1947

Building Sqr. Foot: 694

Bedrooms: 2

Baths Full/Half: 1/0

Basement/Finished: 0/0

Lot Size: 5,900

Zoning: R1

Reception No.: 2004147701

Recording Date: 07/13/04

Document Type: Warranty

Sale Price: 135000

Mill Levy: 64.162

ROSA LOZA
4916 FILLMORE ST 80.00
DENUER CO 80216
02 NOV 8 USA]¢ US EPA-VB/1-10 Projectsite Attention VICTOR KETELLAPPER 10 East 55 ThAVERE DENVER CA 80216 Haldhardan Hallan Maddladda an Illadda

DAMAGED ERT REPLACEMENT NOTICE

Today, we replaced the ERT (the Automatic Meter Reading device attached to your water meter) at your property because it has been damaged. The old ERT is being left with you as evidence of the damage. You may dispose of the ERT as you wish.

This type of damage is typically caused by a lawn mower or lawn aeration equipment, but could also have been caused by a vehicle driving over the ERT, snow removal equipment, or a number of other causes.

Your next bill will contain a charge of \$175, which is our cost for installing a new device. We do not charge for ERTs that stop working where there is no physical damage.

Please be sure to take care when doing yard maintenance near your meter pit. If you have a lawn service, show them where the pit is and ask them to use care, especially when aerating the lawn.

☐ We were unable to obtain a meter reading with:

- We were anable to better a meter reading with
our equipment; your next bill may be based or
an estimate. $8/8/0$
Thanks for your cooperation.
The damage to this ERT appears to be from:

Please dispose of the ERT properly. Denver Water encourages responsible recycling. The stem of the ERT contains AA lithium battery(s) and a small circuit panel that can be removed for recycling. Contact your local recycling agency for proper procedures.

Customer Service file/Forms Adm./12/04



TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1035180

		ONIENT NOMBER. 1000100
SI	TE NAME:	VASQUEZ BOULEVARD AND I-70
DO	DCUMENT DATE:	10/12/2005
Di	ue to one of the fol	DOCUMENT NOT SCANNED
	PHOTOGRAPHS	
	3-DIMENSIONAL	
	OVERSIZED	
Ø	AUDIO/VISUAL	
	PERMANENTLY I	BOUND DOCUMENTS
	POOR LEGIBILIT	Y .
	OTHER	
	NOT AVAILABLE	
		MENTS NOT TO BE SCANNED Data Validation, Sampling Data, CBI, Chain of Custody)
DC	CUMENT DESCR	IPTION:
	2 - DVDs OF PRO	PERTY VIDEO, PROPERTY #3861